RCB5_® POWDER TRICKLER

PRODUCT INSTRUCTIONS

SAFETY

- DO NOT smoke while handling powder.
- Store powder beyond the reach of children and away from heat, dampness, open flames and electrical equipment.
- DO NOT use any powder unless its identity is positively known. Discard all mixed powders and those of uncertain or unknown identity.
- After a reloading session ends, pour the remaining powder back in its original factory container. This will preserve the identity and shelf life of the powder.

GENERAL INFORMATION

The RCBS Powder Trickler provides a fast and easy way to balance a reloading scale when weighing precision powder charges. A twist of the handle will trickle powder into the scale pan a kernel at a time.

The Powder Trickler tube is an ideal height for use with RCBS, or other popular reloading scales.

OPERATING INSTRUCTIONS

To use, fill the large capacity powder reservoir with powder. Several turns of the knob will be required to start the powder feeding through the tube. Then, twist the knob until the desired amount of powder trickles into the scale pan. The powder will be dispensed faster by turning the knob in a clockwise direction.

The Powder Trickler base – designed extra-large to minimize tipping – will accommodate an anchor weight, if desired. Any unused powder should be returned to the original powder container.



We think that we make the very best reloading equipment in the world.

If you agree, please tell your friends.

If you disagree, tell us - we want to do something about it!

Customer Service

1-800-533-5000 (US or Canada) or 530-533-5191

Hours: Monday - Thursday, 6:30am - 3:00pm (hours may vary)

e-mail: rcbs.tech@atk.com • www.rcbs.com

RCBS • 605 Oro Dam Blvd. • Oroville, CA 95965

CCI • SPEER • RCBS
OUTERS • RAMLINE • ORBEX • FEDERAL

7200560/0905